

**TABLE OF CONTENTS**

*Heaters & Sensors* ..... 1

## HEATERS & SENSORS



### 40W HEATER UM2/+

Individually tested heater cable. We know how horrible it is to change it.  
1 Year guarantee. Not recommended for clone blocks.

This product is a consumable and as such has no guarantee, much like tires of a car. If it breaks immediately, it is replaced. 3d Solex however issues a 12 month guarantee.

We know how time consuming it can be to change a heater!

Warning: May not work in "Olsson Block" clone! The calibre of the sensor holes are sometimes out of spec. They need manufacture to tolerances within 6/100 of a millimeter. If the hole is too large, the heaters will not be able to transfer energy, and burn out very brightly inside your block!

[Read More](#)

**SKU:** 7072482000444

**Price:** € 31,00

**Categories:** [Ultimaker 2](#), [Heaters & Sensors](#)



### 35W HEATER UM2/+

Individually tested heater cable. We know how horrible it is to change it.  
1 Year guarantee.

This product is a consumable and as such has no guarantee, much like tires of a car. If it breaks immediately, it is replaced. 3d Solex however issues a 12 month guarantee. We know how time consuming it can be to change a heater!

[Read More](#)

**SKU:** 7072482000420

**Price:** € 28,00

**Categories:** [Ultimaker 2](#), [Heaters & Sensors](#)



### PT100 TEMP SENSOR

Individually tested sensor cable. 1 Year guarantee.

This individually tested Pt100 for UM2/+ is of a high quality.

We issue therefore a 1 year guarantee, even though it is a consumable item. We know how fiddly the changing of this cable is!

Beware of cheap imitations of this quality Chinese product!

[Read More](#)

**SKU:** 7072482000383

**Price:** € 35,00

**Categories:** [Ultimaker 2](#), [Heaters & Sensors](#)



### 50W HEATER UM2/+

Individually tested heater cable. We know how horrible it is to change it.

1 Year guarantee. Not for use on clone blocks.

This product is a consumable and as such has no guarantee, much like tires of a car. If it breaks immediately, it is replaced. 3d Solex however issues a 12 month guarantee.

We know how time consuming it can be to change a heater!

Warning: May not work in "Olsson Block" clone!

The calibre of the sensor holes are sometimes out of spec. They need manufacture to tolerances within 6/100 of a millimeter. If the hole is too large, the heaters will not be able to transfer energy, and burn out very brightly inside your block!

When you have a 50W heater, your head will heat up incredibly fast!

The theoretical downside, is that we cannot guarantee that it will work when there will ever (?) be a dual upgrade for UM2 which needs 2 heaters. It may then be approaching the limit of the available power of the machine.

**Weight** 14 g

**Dimensions** 8 x 6 x 1 cm

[Read More](#)

**SKU:** 7072482000451

**Price:** € 33,00

**Categories:** [Ultimaker 2](#), [Heaters & Sensors](#)